

Notice of References Cited	Application/Control No. 10/021,565	Applicant(s)/Patent Under Reexamination ALLEN ET AL.	
	Examiner Matthew A. Henry	Art Unit 2116	Page 1 of 1

U.S. PATENT DOCUMENTS

*		Document Number Country Code-Number-Kind Code	Date MM-YYYY	Name	Classification
	A	US-2002/0062456	05-2002	Mariaud et al.	713/340
	B	US-5,627,413	05-1997	Mughir et al.	307/86
	C	US-6,633,933	10-2003	Smith et al.	710/74
	D	US-5,477,414	12-1995	Li et al.	361/56
	E	US-			
	F	US-			
	G	US-			
	H	US-			
	I	US-			
	J	US-			
	K	US-			
	L	US-			
	M	US-			

FOREIGN PATENT DOCUMENTS

*		Document Number Country Code-Number-Kind Code	Date MM-YYYY	Country	Name	Classification
	N	FR 2817051 A1	05-2002	France	MARIAUD et al.	G05B 13/02
	O					
	P					
	Q					
	R					
	S					
	T					

NON-PATENT DOCUMENTS

*		Include as applicable: Author, Title Date, Publisher, Edition or Volume, Pertinent Pages)
	U	Apple Computer, Technical Q&A HW82: SDRAM Problems with Self-Powered USB Devices, 2/28/2000, Apple Developer Connection
	V	Apple Computer, Power Macintosh G3 (Blue and White) and G4: Memory Errors, 12/24/1999, Article ID #75016
	W	Davis, Leroy, Logic Design Information: Logic Threshold Levels, 12/31/2000,
	X	STMicroelectronics Microcontroller Division, Monitoring the Vbus Signal for USB Self-Powered Devices, 10/10/2000, STMicroelectronics

*A copy of this reference is not being furnished with this Office action. (See MPEP § 707.05(a).)
Dates in MM-YYYY format are publication dates. Classifications may be US or foreign.